



भारत सरकार
GOVERNMENT OF INDIA
परमाणु ऊर्जा नियामक परिषद
ATOMIC ENERGY REGULATORY BOARD

March 22, 2016

Update on the current situation at KAPS Unit 1 subsequent to the incident of leakage from the coolant system

The detailed plan for isolating the leak was submitted to AERB by NPCIL / KAPS. AERB had reviewed the plan in detail and had given clearance for its implementation with the necessary precautions. The procedure of isolating the leak has been successfully implemented and the leaky channel has now been isolated by the plant. Following this, the plant emergency has been terminated at KAPS.

There has not been any report of abnormal radioactivity releases / radiation exposures to any personnel during this incident, since March 11, 2016.

With the leak completely stopped, investigations for identifying the nature of the leak and its causes can now be taken up. However, it is expected that this could take considerable time.

Presently KAPS Unit 1 is in cold shut down state and all the plant systems are functioning normally.
